

ITS RAINING UP.

ONE EXPLANATION FOR THE PROBLEM SEEMED TO BE THAT SOME OF THE BAFFLES IN THE WATER FLUSHING CHUTE BENEATH THE TOILET SEATS WERE TOO LARGE OR IN THE WRONG PLACE AND EVERY TIME THE AUTOMATIC FLUSHING MECHANISM DUMPED ITS LARGE VOLUME OF WATER INTO THE TROUGH UNDER THE MULTI SEAT ROWS OF THE LADIES RESTROOM THE WATER WAS DIVERTED UP THRU THE TOILET SEAT OPENINGS. THE BAFFLES WERE IN THE TROUGHS TO SLOW DOWN THE SPEED OF THE WATER.

LADIES HAVE WATER ON BOTTOMS COLD WATER TO.

THEY PUT THE SHOWERS IN THE WRONG PLACE WRONG BUILDING

GO IN RESTROOM DRY - COME OUT WET.

GO TO BATHROOM GET CLOTHES WASHED SAME TIME

WE GOT A VERY FUNNY - SERIOUS PROBLEM

THE ONLY PLACE I KNOW WHERE YOU NEED A DIVING SUIT TO GO TO THE BATHROOM IF YOU GOTTA GO - YOU GOTTA KNOW - YOUR GOING TO GET WET.

NO USE GOING TO THE BATHROOM TO KEEP FROM HAVING WET PANTS. THEY HAVE BUILTIN PANTS WETTERS THERE.

THE TOILET SEATS WERE A SERIES OF WATER FOUNTAINS WITH EACH FLUSHING ACTION OF THE AUTOMATIC FLUSHING DEVICE

NOW I KNEW WHY I WONDERED IF IT WOULD WORK WHEN I FIRST SAW THE RUBE GOLDBERG DEVICE.

WE TEMPORARILY CLOSED THE OFFENDING - OUT OF CONTROL TOILET BLDG. PUT A GUARD (TEEN AGE VOLUNTEER) AT THE DOOR WITH INSTRUCTIONS ON WHERE TO SEND ALL LADIES NEEDING EMERGENCY SERVICES And sent THE PLUMBERS INTO THE BUILDING TO CORRECT THE MISSCALCULATIONS THEY REMOVED SOME UNNECCARY BAFFLES THAT WERE DIVERTING THE FLUSHING WATER UPWARDS AND THAT BLOCK BECAME A MORE TRANQUIL PLACE TO LIVE.

THAT SETTLED THE CASE OV THE OVERACTIVE RESTROOM AND STOPPED THE UPSIDE DOWN RAIN.

IT ALSO BROUGHT TO A CLOSE A RASH OF GUARDED AND MUFFLED HILARIOUS CONVERSATION IN MY OFFICE.