

Mr Joy: The hot water system
in the houses is insufficient.
There is not enough hot water
for more than one bath.

After that the hot water runs
cold.

What can we do about
this.

WRA

REC'D NOV 24 1926

2-60 gal boilers each with 2 elec. elements for heating at twice
normal rate
6 baths